

Purchase this vehicle with complete confidence!

(888) 987-7788
sales@nicecarcompany.com

NICE CAR COMPANY

Vehicle Certified by

Herman's Automotive
3350 N. Holland-Sylvania Rd
Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile
24 Month / 30k Mile
36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

Engine

Engine Oil & Filter	Replaced by Herman's Automotive	
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good condition	

Transmission

Fluid	Fluid is clean and color is normal	
Shift Operation	Shift is precise – No apparent slippage	
Differential	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
4x4 Transfer Case	Not applicable to this vehicle	

Brakes

Front Pads	70-80% of Estimated pad life remaining	
Rear Pads/Shoes	70-80% of Estimated pad life remaining	
Front Rotors	Good Condition	
Rear Rotors/Drums	Good Condition	
Brake Calipers	Good Condition	
Wheel Cylinders	Good Condition	
Wheel Hub Assembly	Good Condition	
Master Cylinder	Good Condition	
Wheel Speed Sensors	System operating normally	
Brake Hoses	Good Condition	
Brake Lines	Good Condition	
ABS System	System operating normally	

Steering & Suspension

Stabilizer Links	OEM – But still in very good condition	
Stabilizer Bushings	OEM – But still in very good condition	
Control Arm Bushings	OEM – But still in very good condition	
Steering Column	OEM – But still in very good condition	
Front Struts/Shocks	OEM – But still in very good condition	
Rear Struts/Shocks	OEM – But still in very good condition	
Inner Tie Rods	Good Condition	
Outer Tie Rods	Good Condition	
Universal Joints	OEM – But still in very good condition	
CV Joints & Boots	OEM – But still in very good condition	
Ball Joints	Good Condition	
Springs	OEM – But still in very good condition	
Power Steering Rack	OEM – But still in very good condition	
Power Steering Pump	OEM – But still in very good condition	

Exhaust System

Exhaust Pipe	OEM – But still in very good condition	
Catalytic Converter	OEM – But still in very good condition	
Muffler	OEM – But still in very good condition	
Resonator	OEM – But still in very good condition	
Tail Pipe	OEM – But still in very good condition	

Heating & Cooling System

Antifreeze	Fluid is clean and color is normal	
Belts	Good Condition	
Belt Tensioner	OEM – But still in very good condition	
Water Pump	OEM – But still in very good condition	
Radiator	OEM – But still in very good condition	
Radiator Hoses/Cap	Good Condition	
Fan	OEM – But still in very good condition	
Blower Controls	System operating normally	
Heater Performance	System operating normally	
Heater Hoses	OEM – But still in very good condition	
Air Conditioning	System operating normally	

Completed Updates:

Tire Rotation & Wheel Balance	30.00
Vehicle Inspection Fee	50
Total Reconditioning Costs:	\$80.00

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

Starting / Charging System

Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	

Fuel System

Fuel Tank	System is sound with no apparent leaks	
Fuel Lines	System is sound with no apparent leaks	
Fuel Filter	Good Condition	
Fuel Pump	System operating normally	
Fuel Injectors	System operating normally	

Electrical System

Windshield Wipers	System operating normally	
Windshield Washers	System operating normally	
Radio	System operating normally	
CD Player	Not applicable to this vehicle	
Horn	System operating normally	
Power Windows	Switches and Motors Operating Normally	
Power Locks	Switches and Motors Operating Normally	
Power Seat(s)	Switches and Motors Operating Normally	
Power Trunk	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Liftgate	System operating normally	
Power Mirrors	System operating normally	
GPS/Navigation	System operating normally	
Backup Camera	System operating normally	
Backup Sensors	Not applicable to this vehicle	
DVD Entertainment	Not applicable to this vehicle	
Cruise Control	System operating normally	
Keyless Entry	System operating normally	
Head Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Brake Lights	All Bulbs and switches working properly	
Dimmer Switch	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dash Lights	All Bulbs and switches working properly	
Dome Lights	All Bulbs and switches working properly	
License Plate Light	All Bulbs and switches working properly	
Backup Lights	All Bulbs and switches working properly	
Gauges / Indicators	System operating normally	

Miscellaneous

Front Tires	70-80% of Tread life remaining	
Rear Tires	70-80% of Tread life remaining	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Tire Pressure	Normal Condition	
Alignment	System operating normally	
Spare Tire & Jack	System operating normally	
Wiper Blades	Good Condition	

***** OEM - Original Equipment from the Manufacturer**