Purchase this vehicle with complete confidence!

٧	'eh	icl	е	Ce	rti	fi	e	d	b١	/

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation U	pdate Cost			
Engine					
Engine Management Sensors	OEM - But still in very good condition	1			
Engine Mounts	OEM – But still in very good condition	1 IIII			
Ignition Coil	Good Condition				
Spark Plug Wires	Good Condition				
Spark Plugs	Good Condition				
Vacuum Hoses	OEM – But still in very good condition				
Air Filter	Replaced by Herman's Automotive 27				
Engine Oil & Filter	Replaced by Herman's Automotive	21.50			
Transmission					
4x4 Transfer Case	Not applicable to this vehicle				
Linkage	Not applicable to this vehicle				
Clutch	Not applicable to this vehicle				
Differential	Not applicable to this vehicle				
Shift Operation	Shift is precise – No apparent slippage				
Fluid	Fluid is clean and color is normal				
Brakes					
ABS System	System operating normally				
Brake Lines	Good Condition				
Brake Hoses	Good Condition				
Wheel Speed Sensors	System operating normally				
Master Cylinder	Good Condition				
Wheel Hub Assembly	Good Condition				
Wheel Cylinders	Good Condition				
Brake Calipers	Good Condition				
Rear Rotors/Drums	Good Condition				
Front Rotors	Good Condition				
Rear Pads/Shoes	70-80% of Estimated pad life remaining	na			
Front Pads	70-80% of Estimated pad life remaining				
Steering & Suspension					
Power Steering Pump	OEM – But still in very good condition	1			
Power Steering Rack	OEM - But still in very good condition	ı			
Springs	OEM - But still in very good condition				
Ball Joints	Good Condition				
CV Joints & Boots	OEM – But still in very good condition	1			
Universal Joints	OEM – But still in very good condition				
Outer Tie Rods	Good Condition				
Inner Tie Rods	Good Condition				
Rear Struts/Shocks	OEM – But still in very good condition	n			
Front Struts/Shocks	OEM – But still in very good condition				
Steering Column	OEM – But still in very good condition				
Control Arm Bushings	OEM – But still in very good condition				
Stabilizer Bushings	OEM – But still in very good condition				
Stabilizer Links	OEM – But still in very good condition				
Exhaust System					
Tail Pipe	OEM – But still in very good condition	1			
Resonator	OEM – But still in very good condition				

Muffler

Catalytic Converter Exhaust Pipe

Heating & Cooling System

Housing a booling by bloth		
	Air Conditioning	System operating normally
	Heater Hoses	OEM – But still in very good condition
	Heater Performance	System operating normally
	Blower Controls	System operating normally
	Fan	OEM – But still in very good condition
	Radiator Hoses/Cap	Good Condition
	Radiator	OEM – But still in very good condition
	Water Pump	OEM – But still in very good condition
	Belt Tensioner	OEM – But still in very good condition
	Belts	Good Condition
	Antifreeze	Fluid is clean and color is normal



NICE CAR COMPANY

Completed Updates:				
Tire Rotation & Wheel Balance	30.00			
Air Filter	27.54			
Engine Oil & Filter	21.50			
Vehicle Inspection Fee	50			
Total Reconditioning Costs:	\$129.04			

Component	Mechanics Evaluation	Update Cost		
Starting / Charging System				
Alternator / Regulator	System operating normally			
Starter	System operating normally			
Battery	Good Condition			
,				
Fuel System				
Fuel Injectors	System operating normally			
Fuel Pump	System operating normally			
Fuel Filter	Good Condition			
Fuel Lines	System is sound with no apparen			
Fuel Tank	System is sound with no apparen	nt leaks		
Electrical System				
License Plate Light	All Bulbs and switches working p	roperly		
Dome Lights	All Bulbs and switches working p	roperly		
Dash Lights	All Bulbs and switches working p	roperly		
Turn Signals	All Bulbs and switches working p	roperly		
Dimmer Switch	All Bulbs and switches working p	roperly		
Brake Lights	All Bulbs and switches working p	roperly		
Tail Lights	All Bulbs and switches working p	roperly		
Head Lights	All Bulbs and switches working p	roperly		
Keyless Entry	System operating normally			
Cruise Control	System operating normally			
DVD Entertainment	Not applicable to this vehicle			
Backup Sensors	Not applicable to this vehicle			
Backup Camera	System operating normally			
GPS/Navigation	Not applicable to this vehicle			
Power Mirrors	System operating normally			
Power Liftgate	Not applicable to this vehicle			
Power Sliding Door(s)	Not applicable to this vehicle			
Power Sunroof	Switches and Motors Operating N	Normally		
Power Trunk	Switches and Motors Operating N	Normally		
Power Seat(s)	Switches and Motors Operating N	Normally		
Power Locks	Switches and Motors Operating N	Normally		
Power Windows	Switches and Motors Operating N	Normally		
Horn	System operating normally			
CD Player	System operating normally			
Radio	System operating normally			
Windshield Washers	System operating normally			
Windshield Wipers	System operating normally			
Backup Lights	All Bulbs and switches working properly			
Gauges / Indicators	System operating normally			
Miscellaneous				
Wiper Blades	Good Condition			

Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

*** OEM - Original Equipment from the Manufacturer