Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Er	ngin	ie	
_			 ~=

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Good Condition

Engine Oil & Filter Replaced by Herman's Automotive 21.50

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally

Master Cylinder Good Condition
Wheel Hub Assembly Good Condition
Wheel Cylinders Good Condition
Brake Calipers Good Condition
Rear Rotors/Drums Good Condition
Front Rotors Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks

Front Struts/Shocks

OEM – But still in very good condition

Steering Column

Control Arm Bushings

OEM – But still in very good condition

OEM – But still in very good condition

OEM – But still in very good condition

Stabilizer Bushings

OEM – But still in very good condition

Stabilizer Links

OEM – But still in very good condition

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler Replaced by Herman's Automotive 219.11
Catalytic Converter OEM – But still in very good condition

Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

 Muffler
 219.11

 Engine Oil & Filter
 21.50

 Vehicle Inspection Fee
 50

 Total Reconditioning Costs:
 \$290.61

Component	Mechanics Evaluation	Update Cost
Starting / Charging System		
Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	
Fuel System		
Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no appa	rent leaks
Fuel Tank	System is sound with no appa	rent leaks
Electrical System		
Backup Lights	All Bulbs and switches working	g properly
License Plate Light	All Bulbs and switches working	g properly
Dome Lights	All Bulbs and switches working	g properly
Dash Lights	All Bulbs and switches working	g properly
Turn Signals	All Bulbs and switches working	g properly
Dimmer Switch	All Bulbs and switches working	g properly
Brake Lights	All Bulbs and switches working	g properly
Tail Lights	All Bulbs and switches working	g properly
Head Lights	All Bulbs and switches working	g properly
Keyless Entry	System operating normally	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
Backup Camera	Not applicable to this vehicle	
GPS/Navigation	Not applicable to this vehicle	
Power Mirrors	System operating normally	
Power Liftgate	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Trunk	Not applicable to this vehicle	
Power Seat(s)	Switches and Motors Operating	g Normally
Power Locks	Switches and Motors Operating	g Normally
Power Windows	Switches and Motors Operating	g Normally
Horn	System operating normally	
CD Player	System operating normally	
Radio	System operating normally	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally	
Gauges / Indicators	System operating normally	
Miscellaneous		
Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	

Spare Tire & Jack
System operating normally
Alignment
System operating normally
Normal Condition
Tire Rotation & Wheel Balance
Serviced by Herman's Automotive

Tire Rotation & Wheel Balance Serviced by Herman's Automotive Rear Tires Replaced by Herman's Automotive Front Tires Replaced by Herman's Automotive

*** OEM - Original Equipment from the Manufacturer