

Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive
3350 N. Holland-Sylvania Rd
Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile
24 Month / 30k Mile
36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

Engine

Engine Management Sensors	OEM – But still in very good condition	
Engine Mounts	OEM – But still in very good condition	
Ignition Coil	Good Condition	
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Air Filter	Good Condition	
Engine Oil & Filter	Replaced by Herman's Automotive	21.50

Transmission

4x4 Transfer Case	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
Clutch	Not applicable to this vehicle
Differential	Not applicable to this vehicle
Shift Operation	Shift is precise – No apparent slippage
Fluid	Fluid is clean and color is normal

Brakes

ABS System	System operating normally
Brake Lines	Good Condition
Brake Hoses	Good Condition
Wheel Speed Sensors	System operating normally
Master Cylinder	Good Condition
Wheel Hub Assembly	Good Condition
Wheel Cylinders	Good Condition
Brake Calipers	Good Condition
Rear Rotors/Drums	Good Condition
Front Rotors	Good Condition
Rear Pads/Shoes	70-80% of Estimated pad life remaining
Front Pads	70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump	OEM – But still in very good condition
Power Steering Rack	OEM – But still in very good condition
Springs	OEM – But still in very good condition
Ball Joints	Good Condition
CV Joints & Boots	OEM – But still in very good condition
Universal Joints	OEM – But still in very good condition
Outer Tie Rods	Good Condition
Inner Tie Rods	Good Condition
Rear Struts/Shocks	OEM – But still in very good condition
Front Struts/Shocks	OEM – But still in very good condition
Steering Column	OEM – But still in very good condition
Control Arm Bushings	OEM – But still in very good condition
Stabilizer Bushings	OEM – But still in very good condition
Stabilizer Links	OEM – But still in very good condition

Exhaust System

Tail Pipe	OEM – But still in very good condition
Resonator	OEM – But still in very good condition
Muffler	OEM – But still in very good condition
Catalytic Converter	OEM – But still in very good condition
Exhaust Pipe	OEM – But still in very good condition

Heating & Cooling System

Air Conditioning	System operating normally
Heater Hoses	OEM – But still in very good condition
Heater Performance	System operating normally
Blower Controls	System operating normally
Fan	OEM – But still in very good condition
Radiator Hoses/Cap	Good Condition
Radiator	OEM – But still in very good condition
Water Pump	OEM – But still in very good condition
Belt Tensioner	OEM – But still in very good condition
Belts	Good Condition
Antifreeze	Fluid is clean and color is normal

(888) 987-7788
sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Tire Rotation & Wheel Balance	30.00
Engine Oil & Filter	21.50
Vehicle Inspection Fee	50

Total Reconditioning Costs: \$101.50

Component	Mechanics Evaluation	Update Cost
-----------	----------------------	-------------

Starting / Charging System

Alternator / Regulator	System operating normally
Starter	System operating normally
Battery	Good Condition

Fuel System

Fuel Injectors	System operating normally
Fuel Pump	System operating normally
Fuel Filter	Good Condition
Fuel Lines	System is sound with no apparent leaks
Fuel Tank	System is sound with no apparent leaks

Electrical System

Backup Lights	All Bulbs and switches working properly
License Plate Light	All Bulbs and switches working properly
Dome Lights	All Bulbs and switches working properly
Dash Lights	All Bulbs and switches working properly
Turn Signals	All Bulbs and switches working properly
Dimmer Switch	All Bulbs and switches working properly
Brake Lights	All Bulbs and switches working properly
Tail Lights	All Bulbs and switches working properly
Head Lights	All Bulbs and switches working properly
Keyless Entry	System operating normally
Cruise Control	System operating normally
DVD Entertainment	Not applicable to this vehicle
Backup Sensors	Not applicable to this vehicle
Backup Camera	System operating normally
GPS/Navigation	Not applicable to this vehicle
Power Mirrors	System operating normally
Power Liftgate	Not applicable to this vehicle
Power Sliding Door(s)	Not applicable to this vehicle
Power Sunroof	Not applicable to this vehicle
Power Trunk	Not applicable to this vehicle
Power Seat(s)	Switches and Motors Operating Normally
Power Locks	Switches and Motors Operating Normally
Power Windows	Switches and Motors Operating Normally
Horn	System operating normally
CD Player	Not applicable to this vehicle
Radio	System operating normally
Windshield Washers	System operating normally
Windshield Wipers	System operating normally
Gauges / Indicators	System operating normally

Miscellaneous

Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

*** OEM - Original Equipment from the Manufacturer