# Purchase this vehicle with complete confidence!

**Vehicle Certified by** 

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

## **Extended Warrantys Available**

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
Engine		
Engine Management Sensors	OEM - But still in very good cond	ition
Engine Mounts	OEM - But still in very good condi	ition
Ignition Coil	Good Condition	
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM - But still in very good condi	ition
Air Filter	Good Condition	
Engine Oil & Filter	Replaced by Herman's Automotive	е

Transmission	
4x4 Transfer Case	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
Clutch	Not applicable to this vehicle

Differential Not applicable to this vehicle Shift Operation Shift is precise - No apparent slippage Fluid Fluid is clean and color is normal

### **Brakes**

ABS System System operating normally

**Brake Lines** Good Condition Good Condition Brake Hoses

Wheel Speed Sensors System operating normally Master Cylinder **Good Condition** Wheel Hub Assembly Good Condition Wheel Cylinders Good Condition **Brake Calipers Good Condition** Rear Rotors/Drums **Good Condition** 

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Good Condition

### Steering & Suspension

Front Rotors

OEM - But still in very good condition Power Steering Pump Power Steering Rack OEM - But still in very good condition Springs OEM - But still in very good condition

**Ball Joints Good Condition** 

CV Joints & Boots OEM - But still in very good condition **Universal Joints** OEM - But still in very good condition

Outer Tie Rods **Good Condition** Inner Tie Rods Good Condition Rear Struts/Shocks OEM - But still in very good condition Front Struts/Shocks OEM - But still in very good condition Steering Column OEM - But still in very good condition Control Arm Bushings OEM - But still in very good condition Stabilizer Bushings OEM - But still in very good condition

OEM - But still in very good condition

# Stabilizer Links **Exhaust System**

Tail Pipe OEM - But still in very good condition Resonator OEM - But still in very good condition Muffler OEM - But still in very good condition Catalytic Converter OEM - But still in very good condition OEM - But still in very good condition Exhaust Pipe

#### **Heating & Cooling System**

Air Conditioning System operating normally OEM - But still in very good condition Heater Hoses Heater Performance System operating normally **Blower Controls** System operating normally Fan

OEM - But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM - But still in very good condition Water Pump OEM - But still in very good condition Belt Tensioner OEM - But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

### (888) 987-7788 sales@nicecarcompany.com

## **NICE CAR COMPANY**

# **Completed Updates:**

Tire Rotation & Wheel Balance 30.00 Vehicle Inspection Fee 50 **Total Reconditioning Costs:** \$80.00

Component	Mechanics Evaluation Updat	e Cost
Starting / Charging System		
Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	
Fuel System		
Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no apparent leaks	
Fuel Tank	System is sound with no apparent leaks	
Electrical System		
Gauges / Indicators	System operating normally	
Backup Lights	All Bulbs and switches working properly	
License Plate Light	All Bulbs and switches working properly	
Dome Lights	All Bulbs and switches working properly	
Dash Lights	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dimmer Switch	All Bulbs and switches working properly	
Brake Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Head Lights	All Bulbs and switches working properly	
Keyless Entry	System operating normally	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
Backup Camera	System operating normally	
GPS/Navigation	System operating normally	
Power Mirrors	System operating normally	
Power Liftgate	System operating normally	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Trunk	Not applicable to this vehicle	
Power Seat(s)	Switches and Motors Operating Normally	
Power Locks	Switches and Motors Operating Normally	
Power Windows	Switches and Motors Operating Normally	
Horn	System operating normally	
CD Player Radio	Not applicable to this vehicle	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally System operating normally	
	System operating normally	
Miscellaneous	Cond Condition	
Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment Tire Pressure	System operating normally	
	Normal Condition	20.00
Rear Tires	Serviced by Herman's Automotive 70-80% of Tread life remaining	30.00

\*\*\* OEM - Original Equipment from the Manufacturer

70-80% of Tread life remaining

Front Tires