Purchase this vehicle with complete confidence!

Vehicle Certified by	Extended Wa	rantys Avail
Herman's Automotive	12 Month / 15k M	
3350 N. Holland-Sylvania F	Rd 24 Month / 30k M	/lile
Toledo, OH 43615	36 Month / 36k N	/lile
Component	Mechanics Evaluation	Update Cost
Engine		-
Engine Oil & Filter	Fluid is clean and color is norm	al
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good cor	dition
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good cor	dition
Engine Management Sensors	OEM – But still in very good cor	
	OEM - Dat still in very good cor	
Transmission		
Fluid	Fluid is clean and color is norma	
Shift Operation	Shift is precise – No apparent s	nppage
Differential	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
4x4 Transfer Case	Not applicable to this vehicle	
Brakes		
Front Pads	70-80% of Estimated pad life re	-
Rear Pads/Shoes	70-80% of Estimated pad life re	maining
Front Rotors	Good Condition	
Rear Rotors/Drums	Good Condition	
Brake Calipers	Good Condition	
Wheel Cylinders	Good Condition	
Wheel Hub Assembly	Good Condition	
Master Cylinder	Good Condition	
Wheel Speed Sensors	System operating normally	
Brake Hoses	Good Condition	
Brake Lines	Good Condition	
ABS System	System operating normally	
Steering & Suspension		
Stabilizer Links	OEM – But still in very good cor	ndition
Stabilizer Bushings	OEM – But still in very good cor	ndition
Control Arm Bushings	OEM – But still in very good cor	
Steering Column	OEM – But still in very good cor	ndition
Front Struts/Shocks	OEM – But still in very good cor	
Rear Struts/Shocks	OEM – But still in very good cor	ndition
Inner Tie Rods	Good Condition	
Outer Tie Rods	Good Condition	
Universal Joints	OEM – But still in very good cor	
CV Joints & Boots	OEM – But still in very good cor	ndition
Ball Joints	Good Condition	
Springs	OEM – But still in very good cor	
Power Steering Rack	OEM – But still in very good cor	
Power Steering Pump	OEM – But still in very good cor	ndition
Exhaust System		
Exhaust Pipe	OEM – But still in very good cor	
Catalytic Converter	OEM – But still in very good cor	
Muffler	OEM – But still in very good cor	
Resonator	OEM – But still in very good cor	
Tail Pipe	OEM – But still in very good cor	Iaition

Heating & Cooling System

Antifreeze	Fluid is clean and color is normal	
Belts	Good Condition	
Belt Tensioner	OEM – But still in very good condition	
Water Pump	OEM – But still in very good condition	
Radiator	OEM – But still in very good condition	
Radiator Hoses/Cap	Good Condition	
Fan	OEM – But still in very good condition	
Blower Controls	System operating normally	
Heater Performance	System operating normally	
Heater Hoses	OEM – But still in very good condition	
Air Conditioning	System operating normally	

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates: Vehicle Inspection Fee **Total Reconditioning Costs:**

50 \$50.00

Component	Mechanics Evaluation	Update Cost
Starting / Charging System		-
Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	
Fuel System Fuel Tank	System is sound with no apparent	leaks
Fuel Lines	System is sound with no apparent	
Fuel Filter	Good Condition	leaks
Fuel Pump	System operating normally	
Fuel Injectors		
-	System operating normally	
Electrical System		
Windshield Wipers	System operating normally	
Windshield Washers	System operating normally	
Radio	System operating normally	
CD Player	Not applicable to this vehicle	
Horn	System operating normally	
Power Windows	Switches and Motors Operating No	ormally
Power Locks	Switches and Motors Operating No	ormally
Power Seat(s)	Switches and Motors Operating No	ormally
Power Trunk	Not applicable to this vehicle	
Power Sunroof	Switches and Motors Operating No.	ormally
Power Sliding Door(s)	Not applicable to this vehicle	
Power Liftgate	Not applicable to this vehicle	
Power Mirrors	System operating normally	
GPS/Navigation	Not applicable to this vehicle	
Backup Camera	System operating normally	
Backup Sensors	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Cruise Control	System operating normally	
Keyless Entry	System operating normally	
Head Lights	All Bulbs and switches working pro	operly
Tail Lights	All Bulbs and switches working pro	operly
Brake Lights	All Bulbs and switches working pro	operly
Dimmer Switch	All Bulbs and switches working pro	operly
Turn Signals	All Bulbs and switches working pro	operly
Dash Lights	All Bulbs and switches working pro	operly
Dome Lights	All Bulbs and switches working pro	operly
License Plate Light	All Bulbs and switches working pro	operly
Backup Lights	All Bulbs and switches working pro	operly
Gauges / Indicators	System operating normally	
Miscellaneous		
Front Tires	70-80% of Tread life remaining	
Rear Tires	70-80% of Tread life remaining	
	Serviced by Herman's Automotive	
Tire Pressure	Normal Condition	
Alignment	System operating normally	
Spare Tire & Jack	System operating normally	
Wiper Blades	Good Condition	

*** OEM - Original Equipment from the Manufacturer