Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Engine

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Good Condition

Engine Oil & Filter Replaced by Herman's Automotive 24.95

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally

Master Cylinder Good Condition
Wheel Hub Assembly Good Condition
Wheel Cylinders Good Condition
Brake Calipers Good Condition

Rear Rotors/Drums Replaced by Herman's Automotive 200.58

Front Rotors Good Condition

Rear Pads/Shoes Replaced by Herman's Automotive 56.04

Front Pads 70-80% of Estimated pad life remaining

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks

Front Struts/Shocks

OEM – But still in very good condition

Steering Column

Control Arm Bushings

OEM – But still in very good condition

Stabilizer Bushings

OEM – But still in very good condition

Stabilizer Links

OEM – But still in very good condition

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator

OEM – But still in very good condition

Water Pump

OEM – But still in very good condition

Belt Tensioner

OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Tire Rotation & Wheel Balance 30.00
Rear Rotors/Drums 200.58
Rear Pads/Shoes 56.04
Engine Oil & Filter 24.95
Vehicle Inspection Fee 50

Total Reconditioning Costs: \$361.57

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Battery Good Condition

Fuel System

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

Dome Lights

All Bulbs and switches working properly
Dash Lights

All Bulbs and switches working properly
Turn Signals

All Bulbs and switches working properly
Dimmer Switch

All Bulbs and switches working properly
Brake Lights

All Bulbs and switches working properly
Tail Lights

All Bulbs and switches working properly
Head Lights

All Bulbs and switches working properly
Head Lights

All Bulbs and switches working properly

Keyless Entry

Cruise Control

DVD Entertainment

Backup Sensors

System operating normally

Not applicable to this vehicle

Not applicable to this vehicle

Backup Camera System operating normally
GPS/Navigation System operating normally
Power Mirrors System operating normally
Power Liftgate Not applicable to this vehicle
Power Sliding Door(s) Not applicable to this vehicle

Power Sunroof Switches and Motors Operating Normally
Power Trunk Switches and Motors Operating Normally
Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

HornSystem operating normallyCD PlayerSystem operating normallyRadioSystem operating normallyWindshield WashersSystem operating normallyWindshield WipersSystem operating normally

License Plate Light All Bulbs and switches working properly Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive Rear Tires 70-80% of Tread life remaining

Front Tires 70-80% of Tread life remaining 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer

30.00