## Purchase this vehicle with complete confidence!

| ٧ | eł | ηi | cl | е | C | er | tif | i | e | d | b | v |
|---|----|----|----|---|---|----|-----|---|---|---|---|---|
|   |    |    |    |   |   |    |     |   |   |   |   |   |

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

| Component                 | Mechanics Evaluation U   | pdate Cost |  |  |  |  |
|---------------------------|--|------------|--|--|--|--|
| Engine                    |  |            |  |  |  |  |
| Engine Management Sensors | OEM – But still in very good conditio  | n          |  |  |  |  |
| Engine Mounts             | OEM – But still in very good condition   |            |  |  |  |  |
| Ignition Coil             | Good Condition   |            |  |  |  |  |
| Spark Plug Wires          | Good Condition   |            |  |  |  |  |
| Spark Plugs               | Good Condition   |            |  |  |  |  |
| Vacuum Hoses              | OEM – But still in very good conditio  | n          |  |  |  |  |
| Air Filter                | Good Condition   |            |  |  |  |  |
| Engine Oil & Filter       | Replaced by Herman's Automotive  | 24.95      |  |  |  |  |
| Transmission              |  |            |  |  |  |  |
| 4x4 Transfer Case         | Not applicable to this vehicle   |            |  |  |  |  |
| Linkage                   | Not applicable to this vehicle   |            |  |  |  |  |
| Clutch                    | Not applicable to this vehicle   |            |  |  |  |  |
| Differential              | Not applicable to this vehicle   |            |  |  |  |  |
| Shift Operation           | Shift is precise – No apparent slippa  | ge         |  |  |  |  |
| Fluid                     | Fluid is clean and color is normal   |            |  |  |  |  |
| Brakes                    |  |            |  |  |  |  |
| ABS System                | System operating normally  |            |  |  |  |  |
| Brake Lines               | Good Condition   |            |  |  |  |  |
| Brake Hoses               | Good Condition   |            |  |  |  |  |
| Wheel Speed Sensors       | System operating normally  |            |  |  |  |  |
| Master Cylinder           | Good Condition   |            |  |  |  |  |
| Wheel Hub Assembly        | Good Condition   |            |  |  |  |  |
| Wheel Cylinders           | Good Condition   |            |  |  |  |  |
| Brake Calipers            | Good Condition   |            |  |  |  |  |
| Rear Rotors/Drums         | Good Condition   |            |  |  |  |  |
| Front Rotors              | Good Condition   |            |  |  |  |  |
| Rear Pads/Shoes           | 70-80% of Estimated pad life remain  | ina        |  |  |  |  |
| Front Pads                | 70-80% of Estimated pad life remain  | -          |  |  |  |  |
| Steering & Suspension     |  |            |  |  |  |  |
| Power Steering Pump       | OEM – But still in very good conditio  | n          |  |  |  |  |
| Power Steering Rack       | OEM – But still in very good conditio  |            |  |  |  |  |
| Springs                   | OEM – But still in very good conditio  |            |  |  |  |  |
| Ball Joints               | Good Condition   |            |  |  |  |  |
| CV Joints & Boots         | OEM – But still in very good conditio  | n          |  |  |  |  |
| Universal Joints          | OEM – But still in very good conditio  |            |  |  |  |  |
| Outer Tie Rods            | Good Condition   |            |  |  |  |  |
| Inner Tie Rods            | Good Condition   |            |  |  |  |  |
| Rear Struts/Shocks        | OEM – But still in very good conditio  | n          |  |  |  |  |
| Front Struts/Shocks       | OEM – But still in very good conditio  |            |  |  |  |  |
| Steering Column           | OEM – But still in very good conditio  |            |  |  |  |  |
| Control Arm Bushings      | OEM – But still in very good conditio  |            |  |  |  |  |
| Stabilizer Bushings       | OEM – But still in very good conditio  |            |  |  |  |  |
| Stabilizer Links          | OEM – But still in very good conditio  |            |  |  |  |  |
| Exhaust System            |  |            |  |  |  |  |
| Tail Pipe                 | OEM But still in yony good condition   | n          |  |  |  |  |
| Resonator                 | OEM – But still in very good conditio<br>OEM – But still in very good conditio |            |  |  |  |  |
|                           |  |            |  |  |  |  |

| OLIVI Dut Still III Very good condition |
|---|
| OEM – But still in very good condition  |
| OEM – But still in very good condition  |
| OEM – But still in very good condition  |
| OEM – But still in very good condition  |
|   |

Heating & Cooling System

| ricating a booling bystem |  |
|---------------------------|--|
| Air Conditioning          | System operating normally              |
| Heater Hoses              | OEM – But still in very good condition |
| Heater Performance        | System operating normally              |
| Blower Controls           | System operating normally              |
| Fan                       | OEM – But still in very good condition |
| Radiator Hoses/Cap        | Good Condition                         |
| Radiator                  | OEM – But still in very good condition |
| Water Pump                | OEM – But still in very good condition |
| Belt Tensioner            | OEM – But still in very good condition |
| Belts                     | Good Condition                         |
| Antifreeze                | Fluid is clean and color is normal     |
|                           |  |



## NICE CAR COMPANY

| Completed Updates:            |          |  |  |  |
|-------------------------------|----------|--|--|--|
| Tire Rotation & Wheel Balance | 30.00    |  |  |  |
| Engine Oil & Filter           | 24.95    |  |  |  |
| Vehicle Inspection Fee        | 50       |  |  |  |
| Total Reconditioning Costs:   | \$104.95 |  |  |  |

| Component                  | Mechanics Evaluation                    | Update Cost |  |  |  |
|----------------------------|---|-------------|--|--|--|
| Starting / Charging System |   |             |  |  |  |
| Alternator / Regulator     | System operating normally               |             |  |  |  |
| Starter                    | System operating normally               |             |  |  |  |
| Battery                    | Good Condition                          |             |  |  |  |
| Fuel System                |   |             |  |  |  |
| Fuel Injectors             | System operating normally               |             |  |  |  |
| Fuel Pump                  | System operating normally               |             |  |  |  |
| Fuel Filter                | Good Condition                          |             |  |  |  |
| Fuel Lines                 | System is sound with no apparent leaks  |             |  |  |  |
| Fuel Tank                  | System is sound with no apparer         | nt leaks    |  |  |  |
| Electrical System          |   |             |  |  |  |
| Backup Lights              | All Bulbs and switches working p        | roperly     |  |  |  |
| License Plate Light        | All Bulbs and switches working p        | roperly     |  |  |  |
| Dome Lights                | All Bulbs and switches working p        | roperly     |  |  |  |
| Dash Lights                | All Bulbs and switches working p        | roperly     |  |  |  |
| Turn Signals               | All Bulbs and switches working p        | roperly     |  |  |  |
| Dimmer Switch              | All Bulbs and switches working p        | roperly     |  |  |  |
| Brake Lights               | All Bulbs and switches working p        | roperly     |  |  |  |
| Tail Lights                | All Bulbs and switches working p        | roperly     |  |  |  |
| Head Lights                | All Bulbs and switches working properly |             |  |  |  |
| Keyless Entry              | System operating normally               |             |  |  |  |
| Cruise Control             | System operating normally               |             |  |  |  |
| DVD Entertainment          | Not applicable to this vehicle          |             |  |  |  |
| Backup Sensors             | Not applicable to this vehicle          |             |  |  |  |
| Backup Camera              | Not applicable to this vehicle          |             |  |  |  |
| GPS/Navigation             | Not applicable to this vehicle          |             |  |  |  |
| Power Mirrors              | System operating normally               |             |  |  |  |
| Power Liftgate             | Not applicable to this vehicle          |             |  |  |  |
| Power Sliding Door(s)      | Not applicable to this vehicle          |             |  |  |  |
| Power Sunroof              | Not applicable to this vehicle          |             |  |  |  |
| Power Trunk                | Switches and Motors Operating I         | Normally    |  |  |  |
| Power Seat(s)              | Not applicable to this vehicle          |             |  |  |  |
| Power Locks                | Switches and Motors Operating I         | Normally    |  |  |  |
| Power Windows              | Switches and Motors Operating I         | Normally    |  |  |  |
| Horn                       | System operating normally               |             |  |  |  |
| CD Player                  | System operating normally               |             |  |  |  |
| Radio                      | System operating normally               |             |  |  |  |
| Windshield Washers         | System operating normally               |             |  |  |  |
| Windshield Wipers          | System operating normally               |             |  |  |  |
| Gauges / Indicators        | System operating normally               |             |  |  |  |
| Miscellaneous              |   |             |  |  |  |
| Wiper Blades               | Good Condition                          |             |  |  |  |
| Spare Tire & Jack          | System operating normally               |             |  |  |  |

| Spare Tire & Jack             | System operating normally       |       |
|-------------------------------|---------------------------------|-------|
| Alignment                     | System operating normally       |       |
| Tire Pressure                 | Normal Condition                |       |
| Tire Rotation & Wheel Balance | Serviced by Herman's Automotive | 30.00 |
| Rear Tires                    | 70-80% of Tread life remaining  |       |
| Front Tires                   | 70-80% of Tread life remaining  |       |

## \*\*\* OEM - Original Equipment from the Manufacturer