## Purchase this vehicle with complete confidence!

۷	'eh	icl	е	Ce	rti	fi	e	d	b١	/

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation Upo	date Cost		
Engine				
Engine Management Sensors	<u> </u>			
Engine Mounts	OEM – But still in very good condition			
Ignition Coil	Good Condition			
Spark Plug Wires	Good Condition			
Spark Plugs	Good Condition			
Vacuum Hoses	OEM – But still in very good condition			
Air Filter	Replaced by Herman's Automotive	23.74		
Engine Oil & Filter	Replaced by Herman's Automotive	24.95		
Transmission				
4x4 Transfer Case	Not applicable to this vehicle			
Linkage	Not applicable to this vehicle			
Clutch	Not applicable to this vehicle			
Differential	Not applicable to this vehicle			
Shift Operation	Shift is precise – No apparent slippage			
Fluid	Fluid is clean and color is normal			
Brakes				
ABS System	System operating normally			
Brake Lines	Good Condition			
Brake Hoses	Good Condition			
Wheel Speed Sensors	System operating normally			
Master Cylinder	Good Condition			
Wheel Hub Assembly	Good Condition			
Wheel Cylinders	Good Condition			
Brake Calipers	Good Condition			
Rear Rotors/Drums	Good Condition			
Front Rotors	Good Condition			
Rear Pads/Shoes	60-70% of Estimated pad life remaining			
Front Pads	60-70% of Estimated pad life remaining	1		
Steering & Suspension				
Power Steering Pump	OEM – But still in very good condition			
Power Steering Rack	OEM – But still in very good condition			
Springs	OEM – But still in very good condition			
Ball Joints	Good Condition			
CV Joints & Boots	OEM – But still in very good condition			
Universal Joints	OEM – But still in very good condition			
Outer Tie Rods	Good Condition			
Inner Tie Rods	Good Condition			
Rear Struts/Shocks	OEM – But still in very good condition			
Front Struts/Shocks	OEM – But still in very good condition			
Steering Column	OEM – But still in very good condition			
Control Arm Bushings	OEM – But still in very good condition			
Stabilizer Bushings	OEM – But still in very good condition			
Stabilizer Links	OEM – But still in very good condition			
Exhaust System				
Tail Pipe	OEM – But still in very good condition			
Resonator	OEM – But still in very good condition			

Muffler

Catalytic Converter Exhaust Pipe

OEM – But still in very good condition
OEM – But still in very good condition
OEM – But still in very good condition
OEM – But still in very good condition

Heating & Cooling System

fiedding a oconing cycloin		
	Air Conditioning	System operating normally
	Heater Hoses	OEM – But still in very good condition
	Heater Performance	System operating normally
	Blower Controls	System operating normally
	Fan	OEM – But still in very good condition
	Radiator Hoses/Cap	Good Condition
	Radiator	OEM – But still in very good condition
	Water Pump	OEM – But still in very good condition
	Belt Tensioner	OEM – But still in very good condition
	Belts	Good Condition
	Antifreeze	Fluid is clean and color is normal



## NICE CAR COMPANY

Completed Updates:				
Tire Rotation & Wheel Balance	30.00			
Air Filter	23.74			
Engine Oil & Filter	24.95			
Vehicle Inspection Fee	50			
Total Reconditioning Costs:	\$128.69			

Component	Mechanics Evaluation	Update Cost			
Starting / Charging System					
Alternator / Regulator	System operating normally				
Starter	System operating normally				
Battery	Good Condition				
,					
Fuel System	0 1 1				
Fuel Injectors	System operating normally				
Fuel Pump	System operating normally				
Fuel Filter	Good Condition				
Fuel Lines	System is sound with no apparent leaks				
Fuel Tank	System is sound with no apparent leaks				
Electrical System					
License Plate Light	All Bulbs and switches working p	roperly			
Dome Lights	All Bulbs and switches working p	roperly			
Dash Lights	All Bulbs and switches working properly				
Turn Signals	All Bulbs and switches working properly				
Dimmer Switch	All Bulbs and switches working properly				
Brake Lights	All Bulbs and switches working p	roperly			
Tail Lights	All Bulbs and switches working p	roperly			
Head Lights	All Bulbs and switches working p	roperly			
Keyless Entry	System operating normally				
Cruise Control	System operating normally				
DVD Entertainment	Not applicable to this vehicle				
Backup Sensors	Not applicable to this vehicle				
Backup Camera	Not applicable to this vehicle				
GPS/Navigation	Not applicable to this vehicle				
Power Mirrors	System operating normally				
Power Liftgate	Not applicable to this vehicle				
Power Sliding Door(s)	Not applicable to this vehicle				
Power Sunroof	Not applicable to this vehicle				
Power Trunk	Switches and Motors Operating N	lormally			
Power Seat(s)	Switches and Motors Operating N	lormally			
Power Locks	Switches and Motors Operating N	lormally			
Power Windows	Switches and Motors Operating N	lormally			
Horn	System operating normally				
CD Player	System operating normally				
Radio	System operating normally				
Windshield Washers	System operating normally				
Windshield Wipers	System operating normally				
Backup Lights	All Bulbs and switches working properly				
Gauges / Indicators	System operating normally				
Miscellaneous					
Wiper Blades Good Condition					

Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

## \*\*\* OEM - Original Equipment from the Manufacturer