Purchase this vehicle with complete confidence!

٧	'eh	icl	е	Ce	rti	fi	e	d	b١	/

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation Up	date Cost			
Engine					
Engine Management Sensors	OEM – But still in very good condition				
Engine Mounts	OEM – But still in very good condition				
Ignition Coil	Good Condition				
Spark Plug Wires	Good Condition				
Spark Plugs	Good Condition				
Vacuum Hoses	OEM – But still in very good condition				
Air Filter	Replaced by Herman's Automotive 17.				
Engine Oil & Filter	Replaced by Herman's Automotive	24.95			
Transmission					
4x4 Transfer Case	Not applicable to this vehicle				
Linkage	Not applicable to this vehicle				
Clutch	Not applicable to this vehicle				
Differential	Not applicable to this vehicle				
Shift Operation	Shift is precise – No apparent slippage				
Fluid	Fluid is clean and color is normal				
Brakes					
ABS System	System operating normally				
Brake Lines	Good Condition				
Brake Hoses	Good Condition				
Wheel Speed Sensors	System operating normally				
Master Cylinder	Good Condition				
Wheel Hub Assembly	Good Condition				
Wheel Cylinders	Good Condition				
Brake Calipers	Good Condition				
Rear Rotors/Drums	Good Condition				
Front Rotors	Good Condition				
Rear Pads/Shoes	70-80% of Estimated pad life remainin	g			
Front Pads	70-80% of Estimated pad life remainin	g			
Steering & Suspension					
Power Steering Pump	OEM – But still in very good condition				
Power Steering Rack	OEM - But still in very good condition				
Springs	OEM – But still in very good condition				
Ball Joints	Good Condition				
CV Joints & Boots	OEM – But still in very good condition				
Universal Joints	OEM – But still in very good condition				
Outer Tie Rods	Good Condition				
Inner Tie Rods	Good Condition				
Rear Struts/Shocks	OEM – But still in very good condition				
Front Struts/Shocks	OEM – But still in very good condition				
Steering Column	OEM – But still in very good condition				
Control Arm Bushings	OEM – But still in very good condition				
Stabilizer Bushings	OEM – But still in very good condition				
Stabilizer Links	OEM – But still in very good condition				
Exhaust System					
Tail Pipe	OEM - But still in very good condition				
Resonator	OEM - But still in very good condition				

Tail Pipe	OEM – But still in very good condition
Resonator	OEM – But still in very good condition
Muffler	OEM – But still in very good condition
Catalytic Converter	OEM – But still in very good condition
Exhaust Pipe	OEM – But still in very good condition

Heating & Cooling System

	Air Conditioning	System operating normally
	Heater Hoses	OEM – But still in very good condition
	Heater Performance	System operating normally
	Blower Controls	System operating normally
	Fan	OEM – But still in very good condition
	Radiator Hoses/Cap	Good Condition
	Radiator	OEM – But still in very good condition
	Water Pump	OEM – But still in very good condition
	Belt Tensioner	OEM – But still in very good condition
	Belts	Good Condition
	Antifreeze	Fluid is clean and color is normal



NICE CAR COMPANY

Completed Updates:	Completed Updates:			
Tire Rotation & Wheel Balance	30.00			
Air Filter	17.09			
Engine Oil & Filter	24.95			
Vehicle Inspection Fee	50			
Total Reconditioning Costs:	\$122.04			

Update Cost Component Mechanics Evaluation Starting / Charging System Alternator / Regulator System operating normally Starter System operating normally Battery Good Condition **Fuel System** Fuel Injectors System operating normally Fuel Pump System operating normally Fuel Filter Good Condition Fuel Lines System is sound with no apparent leaks Fuel Tank System is sound with no apparent leaks **Electrical System** License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly Dash Lights All Bulbs and switches working properly All Bulbs and switches working properly Turn Signals Dimmer Switch All Bulbs and switches working properly Brake Lights All Bulbs and switches working properly Tail Lights All Bulbs and switches working properly Head Lights All Bulbs and switches working properly Kevless Entry System operating normally **Cruise Control** System operating normally **DVD** Entertainment Not applicable to this vehicle **Backup Sensors** Not applicable to this vehicle Backup Camera Not applicable to this vehicle GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate Not applicable to this vehicle Power Sliding Door(s) Not applicable to this vehicle Power Sunroof Not applicable to this vehicle Power Trunk Not applicable to this vehicle Power Seat(s) Switches and Motors Operating Normally Switches and Motors Operating Normally Power Locks Power Windows Switches and Motors Operating Normally System operating normally Horn CD Player System operating normally Radio System operating normally Windshield Washers System operating normally Windshield Wipers System operating normally Backup Lights All Bulbs and switches working properly Gauges / Indicators System operating normally Miscellaneous

Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

*** OEM - Original Equipment from the Manufacturer