Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

Spark Plugs Good Condition

Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Replaced by Herman's Automotive 28.49
Engine Oil & Filter Replaced by Herman's Automotive 24.95

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors

Master Cylinder

Wheel Hub Assembly

Wheel Cylinders

Good Condition

Wheel Cylinders

Good Condition

Good Condition

Brake Calipers

Good Condition

Rear Rotors/Drums

Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Good Condition

Steering & Suspension

Front Rotors

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods
Outer Tie Rods
Good Condition
Inner Tie Rods
Good Condition
Rear Struts/Shocks
Front Struts/Shocks
OEM – But still in very good condition
Steering Column
OEM – But still in very good condition
Control Arm Bushings
OEM – But still in very good condition
Stabilizer Bushings
OEM – But still in very good condition
OEM – But still in very good condition

OEM - But still in very good condition

Stabilizer Links Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition Heater Performance System operating normally

Blower Controls System operating normally
Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@ńicecarcompany.com

NICE CAR COMPANY

Completed Updates:

 Tire Rotation & Wheel Balance
 30.00

 Air Filter
 28.49

 Engine Oil & Filter
 24.95

 Vehicle Inspection Fee
 50

 Total Reconditioning Costs:
 \$133.44

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally
Starter System operating normally
Battery Good Condition

Fuel System

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

Gauges / Indicators System operating normally Backup Lights All Bulbs and switches working properly License Plate Light All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly All Bulbs and switches working properly Dash Lights Turn Signals All Bulbs and switches working properly Dimmer Switch All Bulbs and switches working properly All Bulbs and switches working properly **Brake Lights** All Bulbs and switches working properly Tail Lights Head Lights All Bulbs and switches working properly

Keyless Entry System operating normally Cruise Control System operating normally **DVD** Entertainment Not applicable to this vehicle **Backup Sensors** Not applicable to this vehicle Backup Camera Not applicable to this vehicle GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate Not applicable to this vehicle Power Sliding Door(s) Not applicable to this vehicle

Power Trunk Switches and Motors Operating Normally

Not applicable to this vehicle

30.00

Power Seat(s) Not applicable to this vehicle

Power Locks Switches and Motors Operating Normally Power Windows Switches and Motors Operating Normally

Horn System operating normally CD Player System operating normally Radio System operating normally Windshield Washers System operating normally Windshield Wipers System operating normally

Miscellaneous

Power Sunroof

Wiper Blades Good Condition
Spare Tire & Jack System operating normally

Alignment System operating normally

Tire Pressure Normal Condition

Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer