

Purchase this vehicle with complete confidence!

(888) 987-7788
sales@nicecarcompany.com

NICE CAR COMPANY

Vehicle Certified by

Herman's Automotive
3350 N. Holland-Sylvania Rd
Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile
24 Month / 30k Mile
36 Month / 36k Mile

| Component | Mechanics Evaluation | Update Cost |
|---------------------------|--|-------------|
| Engine | | |
| Engine Oil & Filter | Replaced by Herman's Automotive | 39.95 |
| Air Filter | Good Condition | |
| Vacuum Hoses | OEM – But still in very good condition | |
| Spark Plugs | Good Condition | |
| Spark Plug Wires | Good Condition | |
| Ignition Coil | Good Condition | |
| Engine Mounts | OEM – But still in very good condition | |
| Engine Management Sensors | OEM – But still in very good condition | |

| | | |
|---------------------|---|--|
| Transmission | | |
| Fluid | Fluid is clean and color is normal | |
| Shift Operation | Shift is precise – No apparent slippage | |
| Differential | Not applicable to this vehicle | |
| Clutch | Not applicable to this vehicle | |
| Linkage | Not applicable to this vehicle | |
| 4x4 Transfer Case | Not applicable to this vehicle | |

| | | |
|---------------------|---------------------------------|--------|
| Brakes | | |
| Front Pads | Replaced by Herman's Automotive | 58.99 |
| Rear Pads/Shoes | Replaced by Herman's Automotive | 58.99 |
| Front Rotors | Replaced by Herman's Automotive | 227.98 |
| Rear Rotors/Drums | Replaced by Herman's Automotive | 225.98 |
| Brake Calipers | Good Condition | |
| Wheel Cylinders | Good Condition | |
| Wheel Hub Assembly | Good Condition | |
| Master Cylinder | Good Condition | |
| Wheel Speed Sensors | System operating normally | |
| Brake Hoses | Good Condition | |
| Brake Lines | Good Condition | |
| ABS System | System operating normally | |

| | | |
|----------------------------------|--|--|
| Steering & Suspension | | |
| Stabilizer Links | OEM – But still in very good condition | |
| Stabilizer Bushings | OEM – But still in very good condition | |
| Control Arm Bushings | OEM – But still in very good condition | |
| Steering Column | OEM – But still in very good condition | |
| Front Struts/Shocks | OEM – But still in very good condition | |
| Rear Struts/Shocks | OEM – But still in very good condition | |
| Inner Tie Rods | Good Condition | |
| Outer Tie Rods | Good Condition | |
| Universal Joints | OEM – But still in very good condition | |
| CV Joints & Boots | OEM – But still in very good condition | |
| Ball Joints | Good Condition | |
| Springs | OEM – But still in very good condition | |
| Power Steering Rack | OEM – But still in very good condition | |
| Power Steering Pump | OEM – But still in very good condition | |

| | | |
|-----------------------|--|--|
| Exhaust System | | |
| Exhaust Pipe | OEM – But still in very good condition | |
| Catalytic Converter | OEM – But still in very good condition | |
| Muffler | OEM – But still in very good condition | |
| Resonator | OEM – But still in very good condition | |
| Tail Pipe | OEM – But still in very good condition | |

| | | |
|-------------------------------------|--|--|
| Heating & Cooling System | | |
| Antifreeze | Fluid is clean and color is normal | |
| Belts | Good Condition | |
| Belt Tensioner | OEM – But still in very good condition | |
| Water Pump | OEM – But still in very good condition | |
| Radiator | OEM – But still in very good condition | |
| Radiator Hoses/Cap | Good Condition | |
| Fan | OEM – But still in very good condition | |
| Blower Controls | System operating normally | |
| Heater Performance | System operating normally | |
| Heater Hoses | OEM – But still in very good condition | |
| Air Conditioning | System operating normally | |

Completed Updates:

| | |
|-------------------------------|--------|
| Engine Oil & Filter | 39.95 |
| Front Pads | 58.99 |
| Rear Pads/Shoes | 58.99 |
| Front Rotors | 227.98 |
| Rear Rotors/Drums | 225.98 |
| Tire Rotation & Wheel Balance | 30.00 |
| Vehicle Inspection Fee | 50 |

Total Reconditioning Costs: \$691.89

| Component | Mechanics Evaluation | Update Cost |
|-----------------------------------|---------------------------|-------------|
| Starting / Charging System | | |
| Battery | Good Condition | |
| Starter | System operating normally | |
| Alternator / Regulator | System operating normally | |

| | | |
|--------------------|--|--|
| Fuel System | | |
| Fuel Tank | System is sound with no apparent leaks | |
| Fuel Lines | System is sound with no apparent leaks | |
| Fuel Filter | Good Condition | |
| Fuel Pump | System operating normally | |
| Fuel Injectors | System operating normally | |

| | | |
|--------------------------|---|--|
| Electrical System | | |
| Windshield Wipers | System operating normally | |
| Windshield Washers | System operating normally | |
| Radio | System operating normally | |
| CD Player | Not applicable to this vehicle | |
| Horn | System operating normally | |
| Power Windows | Switches and Motors Operating Normally | |
| Power Locks | Switches and Motors Operating Normally | |
| Power Seat(s) | Switches and Motors Operating Normally | |
| Power Trunk | Not applicable to this vehicle | |
| Power Sunroof | Not applicable to this vehicle | |
| Power Sliding Door(s) | Not applicable to this vehicle | |
| Power Liftgate | Not applicable to this vehicle | |
| Power Mirrors | System operating normally | |
| GPS/Navigation | Not applicable to this vehicle | |
| Backup Camera | System operating normally | |
| Backup Sensors | System operating normally | |
| DVD Entertainment | Not applicable to this vehicle | |
| Cruise Control | System operating normally | |
| Keyless Entry | System operating normally | |
| Head Lights | All Bulbs and switches working properly | |
| Tail Lights | All Bulbs and switches working properly | |
| Brake Lights | All Bulbs and switches working properly | |
| Dimmer Switch | All Bulbs and switches working properly | |
| Turn Signals | All Bulbs and switches working properly | |
| Dash Lights | All Bulbs and switches working properly | |
| Dome Lights | All Bulbs and switches working properly | |
| License Plate Light | All Bulbs and switches working properly | |
| Backup Lights | All Bulbs and switches working properly | |
| Gauges / Indicators | System operating normally | |

| | | |
|-------------------------------|---------------------------------|-------|
| Miscellaneous | | |
| Front Tires | 70-80% of Tread life remaining | |
| Rear Tires | 70-80% of Tread life remaining | |
| Tire Rotation & Wheel Balance | Serviced by Herman's Automotive | 30.00 |
| Tire Pressure | Normal Condition | |
| Alignment | System operating normally | |
| Spare Tire & Jack | System operating normally | |
| Wiper Blades | Good Condition | |

***** OEM - Original Equipment from the Manufacturer**