Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation U	pdate Cost
Engine	· · · · · · · · · · · · · · · · · · ·	
Engine Management Sensors	OEM – But still in very good condition]
Engine Mounts	OEM – But still in very good condition	
Ignition Coil	Good Condition	I
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	1
Air Filter	Good Condition	
Engine Oil & Filter	Replaced by Herman's Automotive	34.95
Transmission		
4x4 Transfer Case	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Differential	Not applicable to this vehicle	
Shift Operation	Shift is precise – No apparent slippag	e
Fluid	Fluid is clean and color is normal	
Brakes		
ABS System	System operating normally	
Brake Lines	Good Condition	
Brake Hoses	Good Condition	
Wheel Speed Sensors	System operating normally	
Master Cylinder	Good Condition	
Wheel Hub Assembly	Good Condition	
Wheel Cylinders	Good Condition	
Brake Calipers	Good Condition	
Rear Rotors/Drums	Good Condition	
Front Rotors	Good Condition	
Rear Pads/Shoes	70-80% of Estimated pad life remaining	ng
Front Pads	70-80% of Estimated pad life remaining	ng
Steering & Suspension		
Power Steering Pump	OEM – But still in very good condition) 1
Power Steering Rack	OEM – But still in very good condition	n
Springs	OEM - But still in very good condition	n
Ball Joints	Good Condition	
CV Joints & Boots	OEM – But still in very good condition	n
Universal Joints	OEM – But still in very good condition	ı
Outer Tie Rods	Good Condition	
Inner Tie Rods	Good Condition	
Rear Struts/Shocks	OEM – But still in very good condition	ı
Front Struts/Shocks	OEM – But still in very good condition	
Steering Column	OEM – But still in very good condition	
Control Arm Bushings	OEM – But still in very good condition	
Stabilizer Bushings	OEM – But still in very good condition	
Stabilizer Links	OEM - But still in very good condition	
Exhaust System		
Tail Pipe	OEM – But still in very good condition]
Resonator	OEM – But still in very good condition	

Resonator Muffler

Catalytic Converter

Exhaust Pipe

Heating & Cooling System

Air Conditioning	System operating normally
Heater Hoses	OEM – But still in very good condition
Heater Performance	System operating normally
Blower Controls	System operating normally
Fan	OEM – But still in very good condition
Radiator Hoses/Cap	Good Condition
Radiator	OEM – But still in very good condition
Water Pump	OEM – But still in very good condition
Belt Tensioner	OEM – But still in very good condition
Belts	Good Condition
Antifreeze	Fluid is clean and color is normal



Completed Updates:					
Tire Rotation & Wheel Balance	30.00				
Engine Oil & Filter	34.95				
Vehicle Inspection Fee	50				
Total Reconditioning Costs:	\$114.95				

NICE CAR COMPANY

Component	Mechanics Evaluation	Update Cost
Starting / Charging System	1	
Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	
Fuel System		
Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no appar	rent leaks
Fuel Tank	System is sound with no appar	rent leaks
Electrical System		
Backup Lights	All Bulbs and switches working	g properly
License Plate Light	All Bulbs and switches working	g properly
Dome Lights	All Bulbs and switches working	g properly
Dash Lights	All Bulbs and switches working	g properly
Turn Signals	All Bulbs and switches working	g properly
Dimmer Switch	All Bulbs and switches working	g properly
Brake Lights	All Bulbs and switches working	g properly
Tail Lights	All Bulbs and switches working	g properly
Head Lights	All Bulbs and switches working	g properly
Keyless Entry	System operating normally	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	System operating normally	
Backup Camera	System operating normally	
GPS/Navigation	Not applicable to this vehicle	
Power Mirrors	System operating normally	
Power Liftgate	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Trunk	Switches and Motors Operatin	g Normally
Power Seat(s)	Switches and Motors Operatin	g Normally
Power Locks	Switches and Motors Operatin	g Normally
Power Windows	Switches and Motors Operatin	g Normally
Horn	System operating normally	
CD Player	Not applicable to this vehicle	
Radio	System operating normally	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally	
Gauges / Indicators	System operating normally	
Miscellaneous		
Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alianment	System operating pormally	

Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	

*** OEM - Original Equipment from the Manufacturer