Purchase this vehicle with complete confidence!

Vehicle Certified by	
Herman's Automotive	

3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation U	pdate Cost
Engine		
Engine Management Sensors	OEM - But still in very good condition	۱
Engine Mounts	OEM - But still in very good condition	า
Ignition Coil	Good Condition	
Spark Plug Wires	Good Condition	
Spark Plugs	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	ı
Air Filter	Replaced by Herman's Automotive	35.98
Engine Oil & Filter	Replaced by Herman's Automotive	30.95
Transmission		
4x4 Transfer Case	Not applicable to this vehicle	
Linkage	Not applicable to this vehicle	
Clutch	Not applicable to this vehicle	
Differential	Not applicable to this vehicle	
Shift Operation	Shift is precise - No apparent slippag	je
Fluid	Fluid is clean and color is normal	
Brakes		
ABS System	System operating normally	
Brake Lines	Good Condition	
Brake Hoses	Good Condition	
Wheel Speed Sensors	System operating normally	
Master Cylinder	Good Condition	
Wheel Hub Assembly	Good Condition	
Wheel Cylinders	Good Condition	
Brake Calipers	Good Condition	
Rear Rotors/Drums	Replaced by Herman's Automotive	207.98
Front Rotors	Replaced by Herman's Automotive	223.98
Rear Pads/Shoes	Replaced by Herman's Automotive	58.99
Front Pads	Replaced by Herman's Automotive	58.99
Steering & Suspension		
Power Steering Pump	OEM – But still in very good condition	ו
Power Steering Rack	OEM – But still in very good condition	า
Springs	OEM – But still in very good condition	า
Ball Joints	Good Condition	
CV Joints & Boots	OEM – But still in very good condition	า
Universal Joints	OEM – But still in very good condition	
Outer Tie Rods	Good Condition	
Inner Tie Rods	Good Condition	
Rear Struts/Shocks	OEM – But still in very good condition	ı
Front Struts/Shocks	Replaced by Herman's Automotive	517.98
Steering Column	OEM – But still in very good condition	
Control Arm Bushings	OEM – But still in very good condition	
Stabilizer Bushings	OEM – But still in very good condition	
Stabilizer Links	OEM – But still in very good condition	
Exhaust System		
Tail Pipe	OEM – But still in very good condition	1
Resonator	OEM – But still in very good condition	
Muffler	OEM – But still in very good condition	

Heating & Cooling System

Catalytic Converter

Exhaust Pipe

System operating normally Air Conditioning Heater Hoses OEM - But still in very good condition System operating normally Heater Performance Blower Controls System operating normally Fan OEM – But still in very good condition Radiator Hoses/Cap Good Condition Radiator OEM - But still in very good condition Water Pump OEM - But still in very good condition **Belt Tensioner** OEM - But still in very good condition Belts Good Condition Antifreeze Fluid is clean and color is normal

OEM – But still in very good condition OEM - But still in very good condition



sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:			
Front Struts/Shocks	517.98		
Tire Rotation & Wheel Balance	30.00		
Rear Rotors/Drums	207.98		
Front Rotors	223.98		
Rear Pads/Shoes	58.99		
Front Pads	58.99		
Air Filter	35.98		
Engine Oil & Filter	30.95		
Vehicle Inspection Fee	50		
Total Reconditioning Costs:	\$1,214.85		

Component	Mechanics Evaluation Updat	e Cost
Starting / Charging System		
Alternator / Regulator	System operating normally	
Starter	System operating normally	
Battery	Good Condition	
,		
Fuel System	0 · · · · ·	
Fuel Injectors	System operating normally	
Fuel Pump	System operating normally	
Fuel Filter	Good Condition	
Fuel Lines	System is sound with no apparent leaks	
Fuel Tank	System is sound with no apparent leaks	
Electrical System		
Brake Lights	All Bulbs and switches working properly	
Tail Lights	All Bulbs and switches working properly	
Head Lights	All Bulbs and switches working properly	
Keyless Entry	System operating normally	
Cruise Control	System operating normally	
DVD Entertainment	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
Backup Camera	Not applicable to this vehicle	
GPS/Navigation	Not applicable to this vehicle	
Power Mirrors	System operating normally	
Power Liftgate	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Sunroof	Not applicable to this vehicle	
Power Trunk	Not applicable to this vehicle	
Power Seat(s)	Switches and Motors Operating Normally	
Power Locks	Switches and Motors Operating Normally	
Power Windows	Switches and Motors Operating Normally	
Horn	System operating normally	
CD Player	System operating normally	
Radio	System operating normally	
Windshield Washers	System operating normally	
Windshield Wipers	System operating normally	
Dimmer Switch	All Bulbs and switches working properly	
Turn Signals	All Bulbs and switches working properly	
Dash Lights	All Bulbs and switches working properly	
Dome Lights	All Bulbs and switches working properly	
License Plate Light	All Bulbs and switches working properly	
Backup Lights	All Bulbs and switches working properly	
Gauges / Indicators	System operating normally	
Miscellaneous		
Wiper Blades	Good Condition	
Spare Tire & Jack	System operating normally	
Alignment	System operating normally	
Tire Pressure	Normal Condition	
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive	30.00
Rear Tires	70-80% of Tread life remaining	
Front Tires	70-80% of Tread life remaining	
	-	

*** OEM - Original Equipment from the Manufacturer