

Purchase this vehicle with complete confidence!

(888) 987-7788
sales@nicecarcompany.com

NICE CAR COMPANY

Vehicle Certified by

Herman's Automotive
3350 N. Holland-Sylvania Rd
Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile
24 Month / 30k Mile
36 Month / 36k Mile

| Component | Mechanics Evaluation | Update Cost |
|-----------|----------------------|-------------|
|-----------|----------------------|-------------|

Engine

| | | |
|---------------------------|--|--|
| Engine Oil & Filter | Replaced by Herman's Automotive | |
| Air Filter | Good Condition | |
| Vacuum Hoses | OEM – But still in very good condition | |
| Spark Plugs | Good Condition | |
| Spark Plug Wires | Good Condition | |
| Ignition Coil | Good Condition | |
| Engine Mounts | OEM – But still in very good condition | |
| Engine Management Sensors | OEM – But still in very good condition | |

Transmission

| | | |
|-------------------|---|--|
| Fluid | Fluid is clean and color is normal | |
| Shift Operation | Shift is precise – No apparent slippage | |
| Differential | Not applicable to this vehicle | |
| Clutch | Not applicable to this vehicle | |
| Linkage | Not applicable to this vehicle | |
| 4x4 Transfer Case | Not applicable to this vehicle | |

Brakes

| | | |
|---------------------|--|--|
| Front Pads | 70-80% of Estimated pad life remaining | |
| Rear Pads/Shoes | 70-80% of Estimated pad life remaining | |
| Front Rotors | Good Condition | |
| Rear Rotors/Drums | Good Condition | |
| Brake Calipers | Good Condition | |
| Wheel Cylinders | Good Condition | |
| Wheel Hub Assembly | Good Condition | |
| Master Cylinder | Good Condition | |
| Wheel Speed Sensors | System operating normally | |
| Brake Hoses | Good Condition | |
| Brake Lines | Good Condition | |
| ABS System | System operating normally | |

Steering & Suspension

| | | |
|----------------------|--|--|
| Stabilizer Links | OEM – But still in very good condition | |
| Stabilizer Bushings | OEM – But still in very good condition | |
| Control Arm Bushings | OEM – But still in very good condition | |
| Steering Column | OEM – But still in very good condition | |
| Front Struts/Shocks | OEM – But still in very good condition | |
| Rear Struts/Shocks | OEM – But still in very good condition | |
| Inner Tie Rods | Good Condition | |
| Outer Tie Rods | Good Condition | |
| Universal Joints | OEM – But still in very good condition | |
| CV Joints & Boots | OEM – But still in very good condition | |
| Ball Joints | Good Condition | |
| Springs | OEM – But still in very good condition | |
| Power Steering Rack | OEM – But still in very good condition | |
| Power Steering Pump | OEM – But still in very good condition | |

Exhaust System

| | | |
|---------------------|--|--|
| Exhaust Pipe | OEM – But still in very good condition | |
| Catalytic Converter | OEM – But still in very good condition | |
| Muffler | OEM – But still in very good condition | |
| Resonator | OEM – But still in very good condition | |
| Tail Pipe | OEM – But still in very good condition | |

Heating & Cooling System

| | | |
|--------------------|--|--|
| Antifreeze | Fluid is clean and color is normal | |
| Belts | Good Condition | |
| Belt Tensioner | OEM – But still in very good condition | |
| Water Pump | OEM – But still in very good condition | |
| Radiator | OEM – But still in very good condition | |
| Radiator Hoses/Cap | Good Condition | |
| Fan | OEM – But still in very good condition | |
| Blower Controls | System operating normally | |
| Heater Performance | System operating normally | |
| Heater Hoses | OEM – But still in very good condition | |
| Air Conditioning | System operating normally | |

Completed Updates:

| | |
|------------------------------------|----------------|
| Vehicle Inspection Fee | 50 |
| Total Reconditioning Costs: | \$50.00 |

| Component | Mechanics Evaluation | Update Cost |
|-----------|----------------------|-------------|
|-----------|----------------------|-------------|

Starting / Charging System

| | | |
|------------------------|---------------------------|--|
| Battery | Good Condition | |
| Starter | System operating normally | |
| Alternator / Regulator | System operating normally | |

Fuel System

| | | |
|----------------|--|--|
| Fuel Tank | System is sound with no apparent leaks | |
| Fuel Lines | System is sound with no apparent leaks | |
| Fuel Filter | Good Condition | |
| Fuel Pump | System operating normally | |
| Fuel Injectors | System operating normally | |

Electrical System

| | |
|-----------------------|---|
| Windshield Wipers | System operating normally |
| Windshield Washers | System operating normally |
| Radio | System operating normally |
| CD Player | System operating normally |
| Horn | System operating normally |
| Power Windows | Switches and Motors Operating Normally |
| Power Locks | Switches and Motors Operating Normally |
| Power Seat(s) | Switches and Motors Operating Normally |
| Power Trunk | Not applicable to this vehicle |
| Power Sunroof | Switches and Motors Operating Normally |
| Power Sliding Door(s) | Not applicable to this vehicle |
| Power Liftgate | System operating normally |
| Power Mirrors | System operating normally |
| GPS/Navigation | System operating normally |
| Backup Camera | System operating normally |
| Backup Sensors | Not applicable to this vehicle |
| DVD Entertainment | Not applicable to this vehicle |
| Cruise Control | System operating normally |
| Keyless Entry | System operating normally |
| Head Lights | All Bulbs and switches working properly |
| Tail Lights | All Bulbs and switches working properly |
| Brake Lights | All Bulbs and switches working properly |
| Dimmer Switch | All Bulbs and switches working properly |
| Turn Signals | All Bulbs and switches working properly |
| Dash Lights | All Bulbs and switches working properly |
| Dome Lights | All Bulbs and switches working properly |
| License Plate Light | All Bulbs and switches working properly |
| Backup Lights | All Bulbs and switches working properly |
| Gauges / Indicators | System operating normally |

Miscellaneous

| | |
|-------------------------------|---------------------------------|
| Front Tires | 70-80% of Tread life remaining |
| Rear Tires | 70-80% of Tread life remaining |
| Tire Rotation & Wheel Balance | Serviced by Herman's Automotive |
| Tire Pressure | Normal Condition |
| Alignment | System operating normally |
| Spare Tire & Jack | System operating normally |
| Wiper Blades | Good Condition |

***** OEM - Original Equipment from the Manufacturer**