## Purchase this vehicle with complete confidence!

## **Vehicle Certified by**

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

## **Extended Warrantys Available**

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
Engine		

Engine	
Engine Oil & Filter	Replaced by Herman's Automotive
Air Filter	Good Condition
Vacuum Hoses	OEM – But still in very good condition
Spark Plugs	Good Condition
Spark Plug Wires	Good Condition
Ignition Coil	Good Condition
Engine Mounts	OFM Dut will be seen and a smalleton

**Engine Mounts** OEM – But still in very good condition **Engine Management Sensors** OEM - But still in very good condition

#### **Transmission**

Fluid is clean and color is normal Fluid Shift Operation Shift is precise - No apparent slippage Differential Not applicable to this vehicle Clutch Not applicable to this vehicle Linkage Not applicable to this vehicle 4x4 Transfer Case Not applicable to this vehicle

#### **Brakes**

Front Pads 70-80% of Estimated pad life remaining Rear Pads/Shoes 70-80% of Estimated pad life remaining

Good Condition Front Rotors Rear Rotors/Drums Good Condition **Brake Calipers Good Condition** Wheel Cylinders Good Condition Wheel Hub Assembly Good Condition Master Cylinder **Good Condition** 

Wheel Speed Sensors System operating normally

**Brake Hoses Good Condition Brake Lines** Good Condition

ABS System System operating normally

#### Steering & Suspension

Stabilizer Links OEM - But still in very good condition Stabilizer Bushings OEM - But still in very good condition Control Arm Bushings OEM - But still in very good condition Steering Column OEM – But still in very good condition Front Struts/Shocks OEM - But still in very good condition Rear Struts/Shocks OEM - But still in very good condition Inner Tie Rods **Good Condition** 

Outer Tie Rods Good Condition Universal Joints OEM - But still in very good condition CV Joints & Boots OEM - But still in very good condition **Ball Joints Good Condition** 

Springs OEM - But still in very good condition Power Steering Rack OEM - But still in very good condition Power Steering Pump OEM - But still in very good condition

#### **Exhaust System**

Exhaust Pipe OEM - But still in very good condition Catalytic Converter OEM - But still in very good condition Muffler OEM - But still in very good condition Resonator OEM - But still in very good condition Tail Pipe OEM - But still in very good condition

## **Heating & Cooling System**

Antifreeze Fluid is clean and color is normal Belts Good Condition Belt Tensioner OEM - But still in very good condition Water Pump OEM - But still in very good condition Radiator OEM - But still in very good condition

Radiator Hoses/Cap Good Condition

OEM - But still in very good condition

**Blower Controls** System operating normally Heater Performance System operating normally

Heater Hoses OEM - But still in very good condition

Air Conditioning System operating normally

# (888) 987-7788

sales@nicecarcompany.com

## **NICE CAR COMPANY**

## **Completed Updates:**

Vehicle Inspection Fee 50 **Total Reconditioning Costs:** \$50.00

Component	Mechanics Evaluation	<b>Update Cost</b>
I		

Starting / Charging Suntan	
Starting / Charging System	One di Complision
Battery	Good Condition
Starter	System operating normally
Alternator / Regulator	System operating normally
Fuel System	
Fuel Tank	System is sound with no apparent leaks
Fuel Lines	System is sound with no apparent leaks
Fuel Filter	Good Condition
Fuel Pump	System operating normally
Fuel Injectors	System operating normally
Electrical System	
Windshield Wipers	System operating normally
Windshield Washers	System operating normally
Radio	System operating normally
CD Player	Not applicable to this vehicle
Horn	System operating normally
Power Windows	Switches and Motors Operating Normally
Power Locks	Switches and Motors Operating Normally
Power Seat(s)	Switches and Motors Operating Normally
Power Trunk	Switches and Motors Operating Normally
Power Sunroof	Not applicable to this vehicle
Power Sliding Door(s)	Not applicable to this vehicle
Power Liftgate	Not applicable to this vehicle
Power Mirrors	System operating normally
GPS/Navigation	Not applicable to this vehicle
Backup Camera	System operating normally
Backup Sensors	System operating normally
DVD Entertainment	Not applicable to this vehicle
Cruise Control	System operating normally
Keyless Entry	System operating normally
Head Lights	All Bulbs and switches working properly
Tail Lights	All Bulbs and switches working properly
Brake Lights	All Bulbs and switches working properly
Dimmer Switch	All Bulbs and switches working properly
Turn Signals	All Bulbs and switches working properly
Dash Lights	All Bulbs and switches working properly
Dome Lights	All Bulbs and switches working properly
License Plate Light	All Bulbs and switches working properly
Backup Lights	All Bulbs and switches working properly
Gauges / Indicators	System operating normally
Miscellaneous	
Front Tires	70-80% of Tread life remaining
Rear Tires	70-80% of Tread life remaining
Tire Rotation & Wheel Balance	Serviced by Herman's Automotive
Tire Pressure	Normal Condition

# Good Condition \*\*\* OEM - Original Equipment from the Manufacturer

System operating normally

System operating normally

Alignment

Wiper Blades

Spare Tire & Jack