Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Е	n	gi	n	е
		_		

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

Spark Plugs Good Condition

Vacuum Hoses OEM – But still in very good condition

Air Filter Replaced by Herman's Automotive 32.99
Engine Oil & Filter Replaced by Herman's Automotive 50.95

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

Front Rotors

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors

Master Cylinder

Wheel Hub Assembly

Wheel Cylinders

Good Condition

Rear Rotors/Drums

Good Condition

Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Pads 70-80% of Estimated pad life remaining

Good Condition

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots

OEM – But still in very good condition

Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks
OEM – But still in very good condition
Front Struts/Shocks
OEM – But still in very good condition
Steering Column
OEM – But still in very good condition
Control Arm Bushings
OEM – But still in very good condition
Stabilizer Bushings
OEM – But still in very good condition
Stabilizer Links
OEM – But still in very good condition

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally
Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally
Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@ńicecarcompany.com

NICE CAR COMPANY

\$185.92

Completed Updates:

Wiper Blades21.98Tire Rotation & Wheel Balance30.00Air Filter32.99Engine Oil & Filter50.95Vehicle Inspection Fee50

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Total Reconditioning Costs:

Battery Good Condition

Fuel System

Fuel Injectors System operating normally Fuel Pump System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

Dome Lights

All Bulbs and switches working properly
Dash Lights

All Bulbs and switches working properly
Turn Signals

All Bulbs and switches working properly
Dimmer Switch

All Bulbs and switches working properly
Brake Lights

All Bulbs and switches working properly
Tail Lights

All Bulbs and switches working properly
Head Lights

All Bulbs and switches working properly
Head Lights

All Bulbs and switches working properly

Keyless Entry System operating normally Cruise Control System operating normally **DVD** Entertainment Not applicable to this vehicle **Backup Sensors** System operating normally Backup Camera System operating normally GPS/Navigation Not applicable to this vehicle Power Mirrors System operating normally Power Liftgate System operating normally Power Sliding Door(s) Not applicable to this vehicle Power Sunroof Not applicable to this vehicle

Power Seat(s) Switches and Motors Operating Normally
Power Locks Switches and Motors Operating Normally
Power Windows Switches and Motors Operating Normally

Not applicable to this vehicle

Horn System operating normally
CD Player Not applicable to this vehicle
Radio System operating normally
Windshield Washers System operating normally
Windshield Wipers System operating normally

License Plate Light

All Bulbs and switches working properly

Backup Lights

All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Power Trunk

Wiper Blades Good Condition 21.98

30.00

Spare Tire & Jack System operating normally Alignment System operating normally

Tire Pressure Normal Condition
Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer