Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

12 Month / 15k Mile 24 Month / 30k Mile Month / 36k Mile

Toledo, OTT 43013	30 MONUT / 30K MINE	
Component	Mechanics Evaluation	Update Cost
Engine		
Engine Oil & Filter	Fluid is clean and color is normal	
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good cor	ndition
Transmission		
Fluid	Fluid is clean and color is normal	

(Clutch
ı	Linkage
_	1v/ Transfer Cas

Shift Operation

Differential

Brakes

Front Pads Rear Pads/Shoes Front Rotors

Rear Rotors/Drums **Brake Calipers** Wheel Cylinders Wheel Hub Assembly Master Cylinder

Wheel Speed Sensors Brake Hoses

Brake Lines ABS System

Stabilizer Links Stabilizer Bushings Control Arm Bushings Steering Column

Front Struts/Shocks Rear Struts/Shocks Inner Tie Rods Outer Tie Rods Universal Joints

CV Joints & Boots **Ball Joints** Springs Power Steering Rack Power Steering Pump

Exhaust System Exhaust Pipe Catalytic Converter Muffler

Resonator

Tail Pipe **Heating & Cooling System** Antifreeze

Belts Belt Tensioner Water Pump Radiator

Radiator Hoses/Cap

Blower Controls Heater Performance Heater Hoses Air Conditioning

Shift is precise - No apparent slippage Not applicable to this vehicle Not applicable to this vehicle Not applicable to this vehicle

Not applicable to this vehicle 70-80% of Estimated pad life remaining

70-80% of Estimated pad life remaining Good Condition Good Condition **Good Condition** Good Condition Good Condition

Good Condition System operating normally

Good Condition Good Condition

System operating normally

Steering & Suspension OEM - But still in very good condition OEM - But still in very good condition

OEM - But still in very good condition OEM - But still in very good condition OEM - But still in very good condition OEM - But still in very good condition

Good Condition Good Condition OEM - But still in very good condition OEM - But still in very good condition Good Condition

OEM - But still in very good condition OEM - But still in very good condition OEM - But still in very good condition

OEM - But still in very good condition OEM - But still in very good condition OEM - But still in very good condition OEM - But still in very good condition

OEM - But still in very good condition

Fluid is clean and color is normal

Good Condition OEM - But still in very good condition OEM - But still in very good condition OEM - But still in very good condition

Good Condition

OEM - But still in very good condition System operating normally

System operating normally OEM - But still in very good condition

System operating normally

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

Vehicle Inspection Fee 50 **Total Reconditioning Costs:** \$50.00

Mechanics Evaluation Component **Update Cost**

Starting / Charging System Battery Good Condition

Starter System operating normally Alternator / Regulator System operating normally

Fuel System

Fuel Tank System is sound with no apparent leaks **Fuel Lines** System is sound with no apparent leaks

Fuel Filter Good Condition

Fuel Pump System operating normally **Fuel Injectors** System operating normally

Electrical System

Windshield Winers System operating normally Windshield Washers System operating normally Radio System operating normally **CD Player** Not applicable to this vehicle System operating normally Horn

Power Windows Switches and Motors Operating Normally Power Locks Switches and Motors Operating Normally Power Seat(s) Switches and Motors Operating Normally

Power Trunk Not applicable to this vehicle Power Sunroof Not applicable to this vehicle Power Sliding Door(s) Not applicable to this vehicle Power Liftgate Not applicable to this vehicle Power Mirrors System operating normally GPS/Navigation Not applicable to this vehicle Backup Camera System operating normally **Backup Sensors** Not applicable to this vehicle **DVD** Entertainment Not applicable to this vehicle Cruise Control System operating normally Keyless Entry System operating normally

Head Lights All Bulbs and switches working properly Tail Lights All Bulbs and switches working properly **Brake Lights** All Bulbs and switches working properly Dimmer Switch All Bulbs and switches working properly Turn Signals All Bulbs and switches working properly Dash Lights All Bulbs and switches working properly Dome Lights All Bulbs and switches working properly License Plate Light All Bulbs and switches working properly Backup Lights All Bulbs and switches working properly

Gauges / Indicators System operating normally

Miscellaneous

Front Tires 70-80% of Tread life remaining Rear Tires 70-80% of Tread life remaining Tire Rotation & Wheel Balance Serviced by Herman's Automotive

Tire Pressure Normal Condition

Alignment System operating normally Spare Tire & Jack System operating normally

Winer Blades Good Condition

*** OEM - Original Equipment from the Manufacturer