# Purchase this vehicle with complete confidence!

### **Vehicle Certified by**

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

#### **Extended Warrantys Available**

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	<b>Update Cost</b>
Engine		
Engine Oil & Filter	Fluid is clean and color is norma	al
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good cor	ndition
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	

Ignition Coil	Good Condition
Engine Mounts	OEM – But still in very good condition
Engine Management Sensors	OEM – But still in very good condition

Transmission	
Fluid	Fluid is clean and color is normal
Shift Operation	Shift is precise – No apparent slippage
Differential	Not applicable to this vehicle
Clutch	Not applicable to this vehicle
Linkage	Not applicable to this vehicle
4x4 Transfer Case	Not applicable to this vehicle

Branco		
	Front Pads	70-80% of Estimated pad life remaining
	Rear Pads/Shoes	70-80% of Estimated pad life remaining

Front Rotors	<b>Good Condition</b>
Rear Rotors/Drums	<b>Good Condition</b>
Brake Calipers	<b>Good Condition</b>
Wheel Cylinders	Good Condition
Wheel Hub Assembly	<b>Good Condition</b>
Master Cylinder	Good Condition

Wheel Speed Sensors System operating normally

Brake Hoses Good Condition **Brake Lines** Good Condition ABS System System operating normally

#### Steering & Suspension

Brakes

Stabilizer Links	OEM – But still in very good condition
Stabilizer Bushings	OEM – But still in very good condition
Control Arm Bushings	OEM – But still in very good condition
Steering Column	OEM - But still in very good condition
Front Struts/Shocks	OEM - But still in very good condition
Rear Struts/Shocks	OEM - But still in very good condition
Inner Tie Rods	Good Condition
Outer Tie Rods	Good Condition
Universal Joints	OEM - But still in very good condition
CV Joints & Boots	OEM – But still in very good condition
Ball Joints	Good Condition
Springs	OEM – But still in very good condition
Power Steering Rack	OEM - But still in very good condition
Power Steering Pump	OEM – But still in very good condition
Exhaust System	

•	
Exhaust Pipe	OEM – But still in very good condition
Catalytic Converter	OEM – But still in very good condition
Muffler	OEM – But still in very good condition
Resonator	OEM - But still in very good condition
Tail Pipe	OEM - But still in very good condition

### Heating & Cooling System

3 3	
Antifreeze	Fluid is clean and color is normal
Belts	Good Condition
Belt Tensioner	OEM – But still in very good condition
Water Pump	OEM – But still in very good condition
Radiator	OEM – But still in very good condition
Radiator Hoses/Cap	Good Condition
Fan	OEM – But still in very good condition
Blower Controls	System operating normally
Heater Performance	System operating normally
Heater Hoses	OEM - But still in very good condition
Air Conditioning	System operating normally

# (888) 987-7788

sales@nicecarcompany.com

### **NICE CAR COMPANY**

## **Completed Updates:**

Vehicle Inspection Fee 50 **Total Reconditioning Costs:** \$50.00

Component	Mechanics Evaluation	Update Cost
Starting / Charging System		
Battery	Good Condition	
Starter	System operating normally	
Alternator / Regulator	System operating normally	
Fuel System		
Fuel Tank	System is sound with no apparent le	eaks
Fuel Lines	System is sound with no apparent le	eaks
Fuel Filter	Good Condition	
Fuel Pump	System operating normally	
Fuel Injectors	System operating normally	
Electrical System		
Windshield Wipers	System operating normally	
Windshield Washers	System operating normally	
Radio	System operating normally	
CD Player	System operating normally	
Horn	System operating normally	
Power Windows	Switches and Motors Operating No	rmally
Power Locks	Switches and Motors Operating No	rmally
Power Seat(s)	Not applicable to this vehicle	
Power Trunk	Switches and Motors Operating No	rmally
Power Sunroof	Not applicable to this vehicle	
Power Sliding Door(s)	Not applicable to this vehicle	
Power Liftgate	Not applicable to this vehicle	
Power Mirrors	System operating normally	
GPS/Navigation	Not applicable to this vehicle	
Backup Camera	Not applicable to this vehicle	
Backup Sensors	Not applicable to this vehicle	
DVD Entertainment	Not applicable to this vehicle	
Cruise Control	System operating normally	
Keyless Entry	System operating normally	
Head Lights	All Bulbs and switches working prop	-
Tail Lights	All Bulbs and switches working prop	•
Brake Lights	All Bulbs and switches working prop	perly
Dimmer Switch	All Bulbs and switches working prop	· · · · ·
Turn Signals	All Bulbs and switches working prop	-
Dash Lights	All Bulbs and switches working prop	-
Dome Lights	All Bulbs and switches working prop	•
License Plate Light	All Bulbs and switches working prop	
Backup Lights	All Bulbs and switches working prop	perly
Gauges / Indicators	System operating normally	
Miscellaneous		
Front Tires	70-80% of Tread life remaining	
Rear Tires	70-80% of Tread life remaining	
	Serviced by Herman's Automotive	
Tire Pressure	Normal Condition	
Alignment	System operating normally	
Spare Tire & Jack	System operating normally	
Wiper Blades	Good Condition	

#### \*\*\* OEM - Original Equipment from the Manufacturer