Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available 12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component	Mechanics Evaluation	Update Cost
Engine		
Engine Oil & Filter	Replaced by Herman's Automotive	
Air Filter	Good Condition	
Vacuum Hoses	OEM – But still in very good condition	
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good condition	
Engine Oil & Filter	Replaced by Herman's Automotive 77.96	
Air Filter	Good Condition	
Vacuum Hoses	OEM - But still in very good condit	tion
Spark Plugs	Good Condition	
Spark Plug Wires	Good Condition	
Ignition Coil	Good Condition	
Engine Mounts	OEM – But still in very good condition	
Engine Management Sensors	OEM – But still in very good condition	

Transmission

Fluid Fluid is clean and color is normal Shift Operation Shift is precise - No apparent slippage Differential Not applicable to this vehicle Clutch Not applicable to this vehicle Linkage Not applicable to this vehicle 4x4 Transfer Case Not applicable to this vehicle Fluid Fluid is clean and color is normal Shift Operation Shift is precise - No apparent slippage Differential Not applicable to this vehicle Clutch Not applicable to this vehicle Linkage Not applicable to this vehicle 4x4 Transfer Case Not applicable to this vehicle Brakes Front Pads 70-80% of Estimated pad life remaining Rear Pads/Shoes 70-80% of Estimated pad life remaining Front Rotors Good Condition Rear Rotors/Drums Good Condition Good Condition Brake Calipers Wheel Cylinders Good Condition Wheel Hub Assembly Good Condition Master Cylinder Good Condition Wheel Speed Sensors System operating normally Brake Hoses Good Condition Brake Lines Good Condition ABS System System operating normally Front Pads 50-60% of Estimated pad life remaining 50-60% of Estimated pad life remaining Rear Pads/Shoes Front Rotors Good Condition Rear Rotors/Drums Good Condition **Brake Calipers** Good Condition Wheel Cylinders Good Condition Wheel Hub Assembly Good Condition Master Cylinder Good Condition Wheel Speed Sensors System operating normally Brake Hoses Good Condition Brake Lines Good Condition ABS System System operating normally **Steering & Suspension** Stabilizer Links OEM - But still in very good condition Stabilizer Bushings

Control Arm Bushings Steering Column Front Struts/Shocks Rear Struts/Shocks Inner Tie Rods Outer Tie Rods Universal Joints CV Joints & Boots **Ball Joints** Springs Power Steering Rack

OEM - But still in very good condition Good Condition Good Condition OEM - But still in very good condition OEM - But still in very good condition Good Condition OEM - But still in very good condition OFM - But still in very good condition



sales@nicecarcompany.com

Completed Updates:		
Engine Oil & Filter	77.96	
Tire Rotation & Wheel Balance	40.00	
Vehicle Inspection Fee	50	
Total Reconditioning Costs:	\$167.96	

NICE CAR COMPANY

0	Machanica Frankratian Hadred Cast
Component	Mechanics Evaluation Update Cost
Starting / Charging System	Good Condition
Battery Starter	System operating normally
Alternator / Regulator	System operating normally
Battery	Good Condition
Starter	System operating normally
Alternator / Regulator	System operating normally
Fuel System	
Fuel Tank	System is sound with no apparent leaks
Fuel Lines	System is sound with no apparent leaks
Fuel Filter	Good Condition
Fuel Pump Fuel Injectors	System operating normally System operating normally
Fuel Tank	System is sound with no apparent leaks
Fuel Lines	System is sound with no apparent leaks
Fuel Filter	Good Condition
Fuel Pump	System operating normally
Fuel Injectors	System operating normally
Electrical System	
Windshield Wipers	System operating normally
Windshield Washers	System operating normally
Radio CD Player	System operating normally System operating normally
Horn	System operating normally
Power Windows	Switches and Motors Operating Normally
Power Locks	Switches and Motors Operating Normally
Power Seat(s)	Switches and Motors Operating Normally
Power Trunk	Switches and Motors Operating Normally
Power Sunroof	Not applicable to this vehicle
Power Sliding Door(s)	Not applicable to this vehicle
Power Liftgate	Not applicable to this vehicle
Power Mirrors	System operating normally
GPS/Navigation	Not applicable to this vehicle
Backup Camera Backup Sensors	Not applicable to this vehicle Not applicable to this vehicle
DVD Entertainment	Not applicable to this vehicle
Cruise Control	System operating normally
Keyless Entry	System operating normally
Head Lights	All Bulbs and switches working properly
Tail Lights	All Bulbs and switches working properly
Brake Lights	All Bulbs and switches working properly
Dimmer Switch	All Bulbs and switches working properly
Turn Signals	All Bulbs and switches working properly
Dash Lights Dome Lights	All Bulbs and switches working properly All Bulbs and switches working properly
License Plate Light	All Bulbs and switches working properly
Backup Lights	All Bulbs and switches working properly
Gauges / Indicators	System operating normally
Windshield Wipers	System operating normally
Windshield Washers	System operating normally
Radio	System operating normally
CD Player	Not applicable to this vehicle
Horn	System operating normally
Power Windows Power Locks	Switches and Motors Operating Normally
Power Seat(s)	Switches and Motors Operating Normally Switches and Motors Operating Normally
Power Trunk	Not applicable to this vehicle
Power Sunroof	Not applicable to this vehicle
Power Sliding Door(s)	Not applicable to this vehicle
Power Liftgate	Not applicable to this vehicle
Power Mirrors	System operating normally
GPS/Navigation	Not applicable to this vehicle
Backup Camera	Not applicable to this vehicle
Backup Sensors	Not applicable to this vehicle
DVD Entertainment	Not applicable to this vehicle