Purchase this vehicle with complete confidence!

Vehicle Certified by

Herman's Automotive 3350 N. Holland-Sylvania Rd Toledo, OH 43615

Extended Warrantys Available

29.99

30.95

12 Month / 15k Mile 24 Month / 30k Mile 36 Month / 36k Mile

Component Mechanics Evaluation Update Cost

Engine

Engine Management Sensors OEM – But still in very good condition
Engine Mounts OEM – But still in very good condition

Ignition Coil Good Condition
Spark Plug Wires Good Condition
Spark Plugs Good Condition

Vacuum Hoses
OEM – But still in very good condition
Air Filter
Replaced by Herman's Automotive
Engine Oil & Filter
Replaced by Herman's Automotive

Transmission

 4x4 Transfer Case
 Not applicable to this vehicle

 Linkage
 Not applicable to this vehicle

 Clutch
 Not applicable to this vehicle

 Differential
 Not applicable to this vehicle

 Shift Operation
 Shift is precise – No apparent slippage

 Fluid
 Fluid is clean and color is normal

Brakes

ABS System System operating normally

Brake Lines Good Condition
Brake Hoses Good Condition

Wheel Speed Sensors System operating normally Master Cylinder Good Condition

Wheel Hub Assembly Good Condition
Wheel Cylinders Good Condition
Brake Calipers Good Condition

 Rear Rotors/Drums
 Replaced by Herman's Automotive
 250.98

 Front Rotors
 Replaced by Herman's Automotive
 250.98

 Rear Pads/Shoes
 Replaced by Herman's Automotive
 69.99

 Front Pads
 Replaced by Herman's Automotive
 69.99

Steering & Suspension

Power Steering Pump OEM – But still in very good condition
Power Steering Rack OEM – But still in very good condition
Springs OEM – But still in very good condition

Ball Joints Good Condition

CV Joints & Boots OEM – But still in very good condition
Universal Joints OEM – But still in very good condition

Outer Tie Rods Good Condition
Inner Tie Rods Good Condition

Rear Struts/Shocks
OEM – But still in very good condition
Front Struts/Shocks
OEM – But still in very good condition
Steering Column
OEM – But still in very good condition
Control Arm Bushings
OEM – But still in very good condition
Stabilizer Bushings
OEM – But still in very good condition
Stabilizer Links
OEM – But still in very good condition

Exhaust System

Tail Pipe OEM – But still in very good condition
Resonator OEM – But still in very good condition
Muffler OEM – But still in very good condition
Catalytic Converter OEM – But still in very good condition
Exhaust Pipe OEM – But still in very good condition

Heating & Cooling System

Air Conditioning System operating normally

Heater Hoses OEM – But still in very good condition

Heater Performance System operating normally Blower Controls System operating normally

Fan OEM – But still in very good condition

Radiator Hoses/Cap Good Condition

Radiator OEM – But still in very good condition
Water Pump OEM – But still in very good condition
Belt Tensioner OEM – But still in very good condition

Belts Good Condition

Antifreeze Fluid is clean and color is normal

(888) 987-7788

sales@nicecarcompany.com

NICE CAR COMPANY

Completed Updates:

 Rear Rotors/Drums
 250.98

 Front Rotors
 250.98

 Rear Pads/Shoes
 69.99

 Front Pads
 69.99

 Air Filter
 29.99

 Engine Oil & Filter
 30.95

 Vehicle Inspection Fee
 50

Total Reconditioning Costs: \$752.88

Component Mechanics Evaluation Update Cost

Starting / Charging System

Alternator / Regulator System operating normally Starter System operating normally

Battery Good Condition

Fuel System

Fuel Injectors

System operating normally

Fuel Pump

System operating normally

Fuel Filter Good Condition

Fuel Lines System is sound with no apparent leaks
Fuel Tank System is sound with no apparent leaks

Electrical System

Turn Signals All Bulbs and switches working properly
Dimmer Switch All Bulbs and switches working properly
Brake Lights All Bulbs and switches working properly
Tail Lights All Bulbs and switches working properly

Head Lights All Bulbs and switches working properly
Keyless Entry System operating normally
Cruise Control System operating normally
DVD Entertainment Not applicable to this vehicle

Backup Sensors Not applicable to this vehicle
Backup Camera Not applicable to this vehicle
GPS/Navigation Not applicable to this vehicle
GPS/Navigation Not applicable to this vehicle
Power Mirrors System operating normally
Power Liftgate Not applicable to this vehicle
Power Sliding Door(s) Not applicable to this vehicle
Power Sunroof Not applicable to this vehicle

Power Trunk Switches and Motors Operating Normally

Power Seat(s) Not applicable to this vehicle

Power Locks Switches and Motors Operating Normally Power Windows Switches and Motors Operating Normally

Horn System operating normally
CD Player System operating normally
Radio System operating normally
Windshield Washers System operating normally

Windshield Wipers

Dash Lights

Dome Lights

All Bulbs and switches working properly

All Bulbs and switches working properly

License Plate Light

All Bulbs and switches working properly

All Bulbs and switches working properly

Backup Lights All Bulbs and switches working properly Gauges / Indicators System operating normally

Miscellaneous

Wiper Blades Good Condition
Spare Tire & Jack System operating normally
Alignment System operating normally

Tire Pressure Normal Condition
Tire Rotation & Wheel Balance Serviced by Herman's Automotive
Rear Tires 70-80% of Tread life remaining

Rear Tires 70-80% of Tread life remaining Front Tires 70-80% of Tread life remaining

*** OEM - Original Equipment from the Manufacturer